


Path 1A: Flow Diagram for Control and Test PE Films that employ new resins, additives, coatings, layers, adhesives or blends (Grind then Densify)



Path 1B: Flow Diagram for Control as Resin and Test as Film (Grind then Densify)

