



Appendix I Path 1: Flow Diagram for clear molded articles that employ qualified new resins, additives, coatings, layers, adhesives or blends



This test protocol flow diagrams include a notice of copyright by APR and appear on PFE's website with permission from APR. The flow diagrams provided are summaries of the protocols for illustration of PFE's capabilities. To view the complete test protocol, visit the APR's website at https://plasticsrecycling.org/images/Design-Guidance-Tests/APR-PET-CG-01-critical-guidance.pdf.



Appendix II Path 2: Flow Diagram for Qualified Clear PET Resins



9 of 10 ©2018 Association of Plastic Recyclers. All Rights Reserved plasticsrecycling.org

This test protocol flow diagrams include a notice of copyright by APR and appear on PFE's website with permission from APR. The flow diagrams provided are summaries of the protocols for illustration of PFE's capabilities. To view the complete test protocol, visit the APR's website at https://plasticsrecycling.org/images/Design-Guidance-Tests/APR-PET-CG-01-critical-guidance.pdf.